

Milestone Targets 2009/2010: update December 2009

WELL MAINTAINED	
WM1 To ensure that all public rights of way are easy to use by members of the public (former Best Value Performance Indicator 178). Target for 2009/2010: 95%	To be confirmed
WM2 To carry out major surface improvements or vegetation clearance on 10 public rights of way. (FP =footpath, BR = bridleway, RB = restricted byway)	Bray BR 44 (Gays Lane), and FP 61. Cookham FP 55 (Thames Path), and Byway 68 (Jobs Lane). Hurley BR 15 (Hodgedale Lane). Old Windsor FP 3 (Thames Path). Sunningdale FP 13. Walt. St. Lawrence RB 30 (Downfield Lane) and RB 7. White Waltham RB 8 (Snowball Hill). Total 10
WM3 To repair or replace 5 bridges.	Cookham FP 48 Cox Green FP 6 Maidenhead FP 84 Walt. St. Lawrence FP 38. Total 4
LEGALLY DEFINED	
LD1 To determine a minimum of 4 applications to add public rights of way to the definitive map (claims).	4 claims currently being investigated (Cox Green, Shottesbrooke/Waltham St. Lawrence, White Waltham, Wraysbury)
LD2 To resolve a minimum of 1 significant error in definitive map.	0
WELL PUBLICISED	
WP1 To produce 1 leaflet publicising access opportunities for people with special needs.	0
WP2 To assist others to produce effective promotional material. Target for 2009/10: a minimum of 1 new publication.	Contributing to Thames Path website improvements made by the National Trails Office
IMPROVING ACCESS AND CONNECTIVITY	
AC1 To achieve 1 new route from the Rights of Way Improvement Plan projects	0

<p>AC2 To make physical improvements, including replacement of 27 stiles with gates, to facilitate use by those with special needs, the elderly, people with pushchairs etc.</p>	<p><u>Bray FP 38</u>: stile replaced with "Oxford" kissing gate for medium mobility vehicles. <u>Bray FP 61</u>: four stiles replaced with "Oxford" medium mobility kissing gates. <u>Datchet FP 6</u>: stile replaced with "Woodstock" medium mobility kissing gate. <u>Old Windsor FP 7</u>: utility marker posts and traffic sign re-positioned to improve access to footpath <u>Waltham St. Lawrence FP 38</u>: bridge-stile replaced with "Aston" pedestrian gate and ramp <u>Wraysbury FP 11(rail crossing)</u>: two stiles replaced with "Oxford" medium mobility kissing gates and ramps. Total 10</p>
<p>ENFORCEMENT</p>	
<p>EN 1 To resolve 24 enforcement issues</p> <p><u>Bisham FP 18</u>: electric fencing adj. to stile</p> <p><u>Bisham FP 32</u>: path cropped and not re-instated</p> <p><u>Bray FP 41 and 58</u>: paths not re-instated by SE Water following installation of pipeline</p> <p><u>Eton FP 1</u>: horse riders using/damaging the Thames Path footpath/cycleway</p> <p><u>Eton FPs 4, 17, 18</u>: paths cropped and not re-instated</p> <p><u>Eton FP 19</u>: path cropped and not re-instated</p> <p><u>Maid FP 25A</u>: hedge obscuring FP sign</p> <p><u>Maid FP 44</u>: rat infestation</p> <p><u>Maid BR 46</u>: vehicles using bridleway</p> <p><u>Maid FP 84</u>: garden rubbish dumping</p> <p><u>Walt. St Lawrence FP 41</u>: barbed wire adj. to path</p>	<p><u>Resolved</u></p> <p>Fence non-electrified</p> <p>Path re-instated by landowner</p> <p>Paths re-instated by SE Water</p> <p>Signage erected, horse riders now using adjacent permitted bridleway</p> <p>Paths re-instated by landowner</p> <p>Path re-instated by Council (costs charged to landowner)</p> <p>Hedge cut back by householder</p> <p>Dealt with by pest control</p> <p>Bollard and signage installed</p> <p>Rubbish cleared by householder</p> <p>Barbed wire removed by landowner</p> <p>Total 14</p>

Parish	Number of stiles in the parish
Bisham	1
Bray	54
Cookham	7
Cox Green	6
Datchet	0
Eton	13
Horton	1
Hurley	17
Maidenhead	1
Old Windsor	0
Shottesbrooke	5
Sunningdale	0
Sunninghill	1
Waltham St Lawrence	30
White Waltham	5
Windsor	0
Wraysbury	4
Total	145