

Ramblers Big Pathwatch

All Survey Data



The Big Pathwatch aimed to get everyone out walking paths, checking them and telling us what they found. Between July 2015 to early January 2016, we reported back to you the issues they found. We also received a lot of positive data, which showed why people enjoyed walking and how they valued the right of way network.

This report details everything in the Big Pathwatch found on the right of way network in your area during the reporting period. We hope this provides you with a helpful overview; local Ramblers volunteers will be happy to discuss this in more detail with you. To find your local Ramblers volunteer contact bigpathwatch@ramblers.org.uk or visit <http://www.ramblers.org.uk/go-walking/group-finder.aspx>

The way we work together to protect our paths is very important and we would very much value your feedback on the Big Pathwatch and how it has worked for you. You can provide comments via an online survey - a link to this will be sent shortly in a separate e-mail.

Nicky Philpott
Director of advocacy & engagement

Windsor and Maidenhead (B)

All Survey data

squares adopted:	189
squares completed:	189
km of RoW surveyed:	303.28

features reported:



683



197

This reporting period 13-July-15 to 10-January-16

The report and all data contained in it remains the intellectual property of the Ramblers. It should not be provided to any third party without the prior written consent of the Ramblers. If any extracts are used/published they should be credited accordingly.

For further clarification please see the full terms and conditions on our website by [clicking here](#)

Features reported in Windsor and Maidenhead (B) in the reporting period 13-Jul-15 to 10-Jan-16

Negative Reported Features		Path unusable	Path inconvenient	Total
Intimidating	Dog	0	1	1
	Other	0	6	6
Bridges, gates & stiles	Unsafe stile	0	9	9
	Unsafe gate	0	3	3
	Unsafe bridge	0	4	4
	Other	0	2	2
Finding your way	Missing sign on route	2	19	21
	Missing sign at road	0	13	13
	Broken sign on route	0	1	1
	Broken sign at road	0	3	3
	Discouraging sign	0	1	1
	Path not found	1	3	4
	Other	0	9	9
Path surface	Muddy	0	16	16
	Flooded	0	1	1
	Ploughed	1	9	10
	Other	0	8	8
Road crossing	No safe way to cross	0	4	4
	Other	2	1	3
Obstructions	Undergrowth	2	20	22
	Overhanging vegetation	0	21	21
	Barbed wire (close to path)	0	10	10
	Barbed wire (across path)	0	1	1
	Electric fence (across path)	0	2	2
	Fallen or hanging tree	0	12	12
	Other	2	7	9
Total		10	186	196

Features reported in Windsor and Maidenhead (B) in the reporting period 13-Jul-15 to 10-Jan-16

[FeatureID](#) [Received on](#) [Easting](#) [Northing](#) [GridRef](#)

[Photo URL](#)

[ReporterID](#)

Positive Reported Features		Positive
Attractive views	Woodland	35
	Open country	137
	Town /City	5
	Mountains and hills	2
	Other	34
Fauna	Small mammal	5
	Larger mammals	12
	Birds	63
	Butterfly	5
	Insects	1
Flora	Trees	57
	Flowers	15
	Fungi	10
	Other	22
Interesting	Toilets	2
	Bench	32
	Pub or tea shop	24
	Buildings	41
	Lake or body of water	19
	Other	43
Welcoming	Person	2
	Signs	110
	Other	8
Total		684